٦

Y nSig	ht ECR	L	earn 😨 More	Manheim Digital Marketplac Condition Report Atlanta, GA 30328 (866)626-4346	;e
EHICLE DETA	ILS - 2017 NISSAN TITA	N 4X4 CR PRC)-4X		
IN: xt Color: /ork Order: Service Date:	1N6AA1E53HN501309 BLACK 5011272 N/A	Body Style: Int Color: Seller:	CREW Bla- BLK G MOTORS USA LLC	Top Type:Hard TopOdometer:35,176Received Date:N/A	
			Grade 2 • MSRP-Not • Drivable-Y		
VALUE ADDI Blind Spot M Bluetooth C Dual Zone A Heated Mirr Heated Rea EHICLE INFO	onnection A/C ors ar Seat(s)	 Heated Seats- MP3 Compatib Memory Seats Navigation Sys Rear Parking A 	ole Stèréo stem	Satellite Radio	
OPTIONS	_				
 A/C ABS Brakes AM/FM Ster Automatic Headlights Back up Ca Bed Cover Bedliner Brake Assis System Bucket Sea CD Player Child Safety Cruise Cont 	reo Control Engine Immot Fog Lamps mera Front Floor Ma Front Tow Hoo Intermittent W Keyless Start Keyless Start Leather Steeri Pass-Through	bility ilizer oks ipers Co ng Wheel Rear Sy	Power Windows Pwr Steering Rain Sensing Wipers Rear Floor Mats Security System Sliding Rear Glass Steering Wheel Audio It Steering Tinted Windows Tire Pressure Monitor stem Traction Control Trailer Hitch Receiver	 Trip Computer Turn Signal Mirrors Universal Garage Door Opener 	
MECHANICAL					
 8 Cylinder G Automatic 4X4 5.6 L 	Sas		 Odometer - 6 Digits D Int Odor: OK Leather - BLK 	igital -Operable	
TIRES AND WI	HEELS		KEYS		-1
Wheels:			Smart Key - 2		
Tire Left Front: Left Rear: Right Front:		Size 275/70R18 275/70R18 275/70R18	• Title State: • Title Received Date: r	Free	20 : 2: remium

mmsc400.manheim.com/MABEL/ECR2I.htm?CLIENT=SIMUC&CONFIGID=BUYER&SAUCI=MTCR&SWO=5011272&channel=OVE&listingID=20541... 1/4

	Right Rear:	5/32"	Goodyear	275/70R18
	Spare:	6/32"	Goodyear	275/70R18

ADDITIONAL INFORMATION



_						
<u> Ope</u>	n All Damages [🔺 Cl	lose All Damages				
🔺 Co	smetic Conventional	Paint and Body Not R	equired-[4 Items]			
MAGE	DESCRIPTION	CONDITION	SEVERITY			
	Front Bumper	Prev Repair	Acceptable			
	Grille	Prev Repair	Acceptable			
	LR Door	Chipped	4			
	R Bed Side	Chipped	4			
🔺 Mir	nor Damages Conver	ntional Repairs May Bo	e Required-[2 Items]			
MAGE	DESCRIPTION	CONDITION	SEVERITY			
	Rear Bumper	Chipped	4			
	Tailgate	Dent/Paint Dmg	1/2" to 1"			
Str	ructural-[1 Items]					
MAGE	DESCRIPTION	CONDITION	SEVERITY			
	L "A" Pillar	Prev Repair	Acceptable			
A Pre	evious Repair-[3 Item	ıs]				
MAGE	DESCRIPTION	CONDITION	SEVERITY			
	Hood	Prev Repair	Acceptable			
	LF Door	Prev Repair	Acceptable			
	LF Fender	Prev Repair	Acceptable			
Mis	scellaneous-[7 Items		·			
MAGE	DESCRIPTION	CONDITION	SEVERITY			
			-			
and the second	Left Fog Light	Missing	Replacement Required			
and the second						
	LF Window	Inop	Repair Required			
	Owners manuals	Missing	Replacement Required			
	RF Mirror Housing	Broken	Replacement Required			
	Right Fog Light	Missing	Replacement Required			
		Wissing	Replacement Required			
	Sec. 1					
	Spare Tire	Missing	Replacement Required			
		-				
4 3 200000 5						
7 S * 7	Warning - Airbag	On	Unacceptable			
A Me	chanical-[1 Items]					
MAGE	DESCRIPTION	CONDITION	SEVERITY			
	F Bumper Sensors	Missing	Replacement Required			
			,			
MAGE	DESCRIPTION	CONDITION	SEVERITY			
<u>riter</u> (23:20	: 25
UER	2 0000 Picture# 1	Overall Picture		Free		
				שרוכפ	Get Prem	ium
	0000 Picture# 2					

mmsc400.manheim.com/MABEL/ECR2I.htm?CLIENT=SIMUC&CONFIGID=BUYER&SAUCI=MTCR&SWO=5011272&channel=OVE&listingID=20541... 3/4

0000 Picture# 3	Overall Picture	
0000 Picture# 4	Overall Picture	
0000 Picture# 5	Overall Picture	
0000 Picture# 6	Overall Picture	
0000 Picture# 7	Overall Picture	
0000 Picture# 8	Overall Picture	
0000 Picture# 9	Overall Picture	
0000 Picture# 10	Overall Picture	
0000 Picture# 11	Overall Picture	
0000 Picture# 12	Overall Picture	
0000 Picture# 13	Overall Picture	
0000 Picture# 14	Overall Picture	
0000 Picture# 15	Overall Picture	
0000 Picture# 16	Overall Picture	
0000 Picture# 17	Overall Picture	
0000 Picture# 18	Overall Picture	
VIN: 1N6AA1E53HN501309, Wo	ork Order: 5011272	

