




2014 MERCEDES ML550W4 ML550

VIN 4JGDA7DB1EA276641
 Ext Color WHITE- 799
 Work Order 6440556
 Sale Number 6
 CR Date 01/10/2020

Body Style
 Int Color
 Seller
 Lane Number
 InService Date:



[All Images \(29\)](#) [Exterior \(6\)](#) [Interior \(8\)](#) [Misc \(4\)](#) [Damages \(11\)](#)



VEHICLE INFORMATION

HIGH VALUE OPTIONS

- Auxiliary Audio Input
- Back-Up Camera
- Blind Spot Monitor
- Bluetooth Connection
- CD Changer
- Dual Zone A/C
- Heated Mirrors
- Heated Seats-Front(s)
- Lane Departure System
- Leather Seats
- Navigation System
- Panoramic Roof

OPTIONS

- 5 Passenger Seating
- A/C
- Automatic Headlights
- Brake Assist System
- Bucket Seats
- CD Player
- Cargo Shade
- Child Safety Locks
- Climate Control
- Cruise Control
- Daytime Running Lights
- Driver Adjustable Lumbar
- Driver Air Bag
- Driver Illuminated Vanity Mirror
- Driver Vanity Mirror
- Dual Air Bags
- Electrochromic Rearview Mirror
- Electronic Stability Control
- Engine Immobilizer
- Fog Lamps
- Front Floor Mats
- Front Head Air Bag
- Front Side Air Bag
- HD Radio
- Heated Steering Wheel
- Intermittent Wipers
- Keyless Entry
- Knee Air Bag
- Lane Departure Intervention
- Leather Steering Wheel
- Luggage Rack
- Mirror Memory
- Pass-Through Rear Seat
- Passenger Air Bag Sensor
- Passenger Illuminated Vanity Mirror
- Passenger Vanity Mirror

MECHANICAL

- 8 Cylinder Gas Turbo
- Automatic
- AWD
- Automatic Transmission
- Anti-lock Brakes
- 4.7 L

TIRES AND WHEELS

Wheels:	Alloy		
Tire		Tread Depth	Brand
Left Front:		4/32"	PIRELLI
Left Rear:		4/32"	PIRELLI
Right Front:		4/32"	PIRELLI
Right Rear:		2/32"	PIRELLI
Spare:		N/A	(Mini)

ADDITIONAL INFORMATION

ANNOUNCEMENTS

AWD;NAV;ENG LT ON +\$500,


DAMAGE SUMMARY AND ADDITIONAL IMAGES

Open All Damages

Close All Damages



Condition Heat Map



Cosmetic Conventional Paint and Body Not Required-[2 Items]

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	L Qtr Panel	Dent/No Paint Dmg	PDR/1
	R Qtr Panel	Mult Dents/No Paint Dmg	PDR/3



Previous Repair-[8 Items]

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Front Bumper	Prev Repair	Acceptable
	Hood	Replaced	Acceptable
	LF Fender	Prev Repair	Acceptable
	LR Door	Prev Repair POOR PDR	Acceptable
	Rear Bumper	Prev Repair	Acceptable
	RF Door	Prev Repair	Acceptable
	RF Fender	Prev Repair	Acceptable
	RR Door	Prev Repair	Acceptable



Miscellaneous-[10 Items]

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Emissions Sticker	Missing	Replacement Required
	F Valance	Dent/No Paint Dmg	1/2" to 1"
	LF Wheel	Curb Rash	GR 12"
	LR Wheel	Curb Rash	7" to 8"
	Owners manuals	Missing	Replacement Required
	RR Tire	Worn	Replacement Required
	RR Wheel	Curb Rash	GR 12"
	Warning - Engine	Inop	
	Warning - Engine	On	Unacceptable
	Warranty Books	Missing	Replacement Required

*Process protected under U.S. Patent No. 8,230,362

VIN: 4JGDA7DB1EA276641, Work Order: 6440556