0.02.2021				
Sight ECR)		Learn 😨 More		Manheim 3rd Party Cl Condition Report Atlanta, GA 30328 (866)626-4346
VEHICLE DETAILS - 2020 AUDI A8 L Bas VIN: WAU8EAF85LN002709 Ext Color: WHITE Work Order: 5217444 InService Date: N/A	Body Style: Int Color: Seller:	4DSN Tan- TAN HGREG LUX	Top Type: Odometer: Received Date:	Dual Sunroofs 134 N/A
<image/>		• MSRP • Driva	Auto@Gra Grade 5.0 Extr -Not Available ble-Yes	a Clean
VALUE ADDED OPTIONS Auto Leveling Headlights Blind Spot Monitor Bluetooth Connection Cooled Front Seat(s) Dual Zone A/C Hard Disk Drive Media Storage VEHICLE INFORMATION	 Heads-Up Heated Mir Heated Reated Reated Seated Heated Seated Seated Lane Depa MP3 Comp 	rors ar Seat(s) ats-Front(s) rture System	 Memory Navigation Premium Rear Part Satellite I Telemation 	on System Stereo king Aid Radio
 OPTIONS A/C ABS Brakes Automatic Headlights Back up Camera Brake Assist System Bucket Seats Child Safety Locks Cruise Control Daytime Running Lights Dual Air Conditioning Electrochromid Bit Electronic Stal Electronic Stal Electronic Stal Electronic Stal Engine Immob Foot Floor Ma Heated Steerin Intermittent W Keyless Entry Leather Steerin 	bility Control ilizer ats ng Wheel ipers	Mirror Memory Pass-Through Rea Power Folding Mir Power Mirrors Power Windows Pwr Steering Rain Sensing Wip Rear Floor Mats Security System Steering Wheel Au ontrol	ar Seat Tire rors System Trac Trip Turr ers Univ Opener Woo	ction Control Computer n Signal Mirrors versal Garage Door odgrain Interior
MECHANICAL • 8 Cylinder Gas • Automatic • AWD • 4.0 L		INTERIOR Odometer - 6 I Int Odor: OK Leather - TAN	Digits Digital -Opera	able
	Size 55/40R20 55/40R20	• Smart Key - 1 • OTHER • Title State: • Title Received	Date: N/A	

25.02.2021

DAMAGE SUMMARY AND ADDITIONAL IMAGES						
Open All Damages Close All Damages						
IMAGE	DESCRIPTION	CONDITION	SEVERITY			
	0000 Picture# 1	Overall Picture				
	0000 Picture# 2	Overall Picture				
	0000 Picture# 3	Overall Picture				
	0000 Picture# 4	Overall Picture				
	0000 Picture# 5	Overall Picture				
	0000 Picture# 6	Overall Picture				
	0000 Picture# 7	Overall Picture				
	0000 Picture# 8	Overall Picture				
	0000 Picture# 9	Overall Picture				
	0000 Picture# 10	Overall Picture				
	0000 Diatura# 11	Overall Picture				
	0000 Picture# 11	Overall Picture				
	0000 Picture# 12	Overall Picture				
	0000 Picture# 13	Overall Picture				
	0000 Picture# 14	Overall Picture				
	0000 Picture# 15	Overall Picture				
	0000 Picture# 16	Overall Picture				
	0000 Picture# 17	Overall Picture				
VIN: WAU8	VIN: WAU8EAF85LN002709, Work Order: 5217444					