

Condition Report

VOLKSWAGEN CLEAR LAKE

CR Date: 09-10-2020

2018 Volkswagen ATLAS SUV

VEHICLE INFORMATION



CR Date:

09-10-2020

Seller:

VOLKSWAGEN CLEAR LAKE

Year:

2018

Make:

Volkswagen

Model:

ATLAS

Style:

SUV

VIN:

1V2NR2CA3JC540842

Drive:

ALL-WHEEL DRIVE

Body Type:

Engine:

3.6L

Transmission:

AUTOMATIC

Odometer:

47416

Exterior Color:

WHITE

Interior Color:

Vehicle Type:

Other

NAAA Grade:

4.2

VEHICLE INFORMATION

AIRCONDITIONER

POWERSTEERING

SECURITYSYSTEM

LEATHER INTERIOR

POWERWINDOWS

TILTWHEEL

POWERBRAKES

RADIOAMFM

VEHICLE ANNOUNCEMENTS

Title Status: Title Absent

Odometer State: No Issues

Check Engine Light: No

Hail Damage: No

Taxi Use: No

Smoker: Unknown

Canadian Vehicle: No

Exhaust Altered: No

Limited Arbitration Power Train Pledge: No

Keys: Unknown

Title State: Unknown

FrameDamage: No

Flood Damage: No

Theft Recovery: No

Police Use: No

General Odor: No

VIN Plate Issue: No

Suspension Altered: No

Airbag Light On: No

Key Fobs: Unknown

Driveable: Yes

Airbags Deployed: No

Fire Damage: No

Livery Use: No

Grey Market: No

Has Manuals: No


Warranty Cancelled: No

Tire Pressure Indicator Warning: No

Airbag Missing: No

Additional Notes: GREEN LIGHTVEH REPORTED AS TOTAL LOSS GREEN LIGHT VEH REPORTED AS TOTAL LOSS

VEHICLE DAMAGES



LOCATION

Right Rear Door

DAMAGE TYPE

Dents W/No Pt. Dmg.

SEVERITY

DESCRIPTION

Repair Required



DAMAGE PHOTOS



Repair Required

VEHICLE TIRES

FRONT LEFT TIRE

Condition: Good

Brand: Other

Tread Depth: 4/32"

Size: 20"

FRONT RIGHT TIRE

Condition: Fair

Brand: Other

Tread Depth: 3/32"

Size: 20"

REAR LEFT TIRE

Condition: Good

Brand: Other

Tread Depth: 5/32"

Size: 20"

REAR RIGHT TIRE

Condition: Good

Brand: Other

Tread Depth: 4/32"

Size: 20"



SPARE TIRE

Condition: N/A

Brand:

Tread Depth:

Size:

VEHICLEPHOTOS







