



Learn More

Manheim 3rd Party CR  
Condition Report  
Atlanta, GA 30328  
(866)626-4346

VEHICLE DETAILS - 2019 MERCEDES GLC300C4 GLC 300

VIN: WDC0J4KB2KF585676 Body Style: 4DSN Top Type: Sun Roof  
 Ext Color: SILVER Int Color: Bla- BLK Odometer: 19,539  
 Work Order: 5198132 Seller: COMMONWEALTH MOTOR INC Received Date: N/A  
 InService Date: N/A

GRADING



Grade 4.5 Clean

- MSRP-Not Available
- Drivable-Yes

\*Process protected under U.S. Patent No. 8,230,362

VALUE ADDED OPTIONS

- Bluetooth Connection
- Heated Seats-Front(s)
- Navigation System
- Dual Zone A/C
- MP3 Compatible Stereo
- Premium Stereo
- Heated Mirrors
- Memory Seats
- Telematics

VEHICLE INFORMATION

OPTIONS

- A/C
- ABS Brakes
- AM/FM Stereo
- Automatic Headlights
- Back up Camera
- Brake Assist System
- Bucket Seats
- CD Player
- Cargo Shade
- Child Safety Locks
- Cruise Control
- Daytime Running Lights
- Electrochromic Rearview Mirror
- Electronic Stability Control
- Engine Immobilizer
- Front Floor Mats
- HD Radio
- Intermittent Wipers
- Keyless Entry
- Keyless Start
- Leather Steering Wheel
- Mirror Memory
- Pass-Through Rear Seat
- Power Folding Mirrors
- Power Liftgate
- Power Mirrors
- Power Windows
- Pwr Steering
- Rain Sensing Wipers
- Rear Floor Mats
- Remote Trunk Release
- Security System
- Steering Wheel Audio Control
- Tilt Steering
- Tinted Windows
- Tire Pressure Monitor System
- Traction Control
- Trip Computer
- Turn Signal Mirrors
- Universal Garage Door Opener
- Woodgrain Interior Package

MECHANICAL

- 4 Cylinder Gas
- Automatic
- AWD
- 2.0 L

INTERIOR

- Odometer - 6 Digits Digital -Operable
- Int Odor: OK
- Vinyl - BLK

TIRES AND WHEELS

Wheels:

Tire	Tread Depth	Brand	Size
Left Front:	5/32"	Continental	235/55R19
Left Rear:	6/32"	Continental	235/55R19
Right Front:	5/32"	Continental	235/55R19
Right Rear:	6/32"	Continental	235/55R19
Spare:	10/32"	Other	255/30R18

KEYS

- Smart Key - 2

OTHER

- Title State:
- Title Received Date: N/A

ADDITIONAL INFORMATION

**DAMAGE SUMMARY AND ADDITIONAL IMAGES**

Open All Damages  Close All Damages



**Cosmetic Conventional Paint and Body Not Required**

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Hood	Chipped	2



**Minor Damages Conventional Repairs May Be Required**

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Front Bumper	Chipped	2
	Rear Bumper	Chipped	1
	RR Door	Light Mult Scratches	3



**Miscellaneous**

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	LF Door Edge	Edge Chipped	1
	RF Wheel	Curb Rash	5" to 6"

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	0000 Picture# 1	Overall Picture	
	0000 Picture# 2	Overall Picture	
	0000 Picture# 3	Overall Picture	
	0000 Picture# 4	Overall Picture	
	0000 Picture# 5	Overall Picture	
	0000 Picture# 6	Overall Picture	
	0000 Picture# 7	Overall Picture	
	0000 Picture# 8	Overall Picture	

0000 Picture# 9	Overall Picture
0000 Picture# 10	Overall Picture
0000 Picture# 11	Overall Picture
0000 Picture# 12	Overall Picture
0000 Picture# 13	Overall Picture
0000 Picture# 14	Overall Picture
0000 Picture# 15	Overall Picture
0000 Picture# 16	Overall Picture
0000 Picture# 17	Overall Picture
0000 Picture# 18	Overall Picture
0000 Picture# 19	Overall Picture

**VIN: WDC0J4KB2KF585676, Work Order: 5198132**