



2017 MERCEDES-BENZ GLC GLC 300

WDC0G4KB7HV004833 • Odo 21 489  
Polar White / Silk Beige/Black • 4\_CYLINDER • AUTOMATIC • All Wheel Drive  
AUTOTYM INC



Announcements      Remarks/Comments

Green Light /  
Guaranteed  
Prior Paint      --

Title

TITLE STATE	NJ
TITLE STATUS	WITH SELLER
TITLE BRANDINGS	CLEAN

Issues

EXTERIOR	2
INTERIOR	0
MECHANICAL	0

INSPECTION

Exterior

! BODY PANELS WITH LIGHT DENTS AND SCRATCHES  
1

! PRIOR PAINT  
Yes

BODY PANELS WITH SUBSTANDARD PREVIOUS REPAIRS AND PAINT  
None

BODY PANELS THAT NEED REPAIRS BUT NOT REPLACEMENT

None

BODY PANELS THAT NEED REPLACEMENT

None

BUMPERS THAT NEED REPLACEMENT

No

VEHICLE LIGHTS DAMAGE

No

FRAME/STRUCTURAL

No

STRUCTURAL ALTERATIONS

No

PAINTED BODY PANELS WITH RUST

None

RUST AFFECTING SHAPE, INTEGRITY OR THICKNESS (INCLUDING UNDERCARRIAGE)

No

HAIL DAMAGE

None

VEHICLE GLASS OR WINDSHIELD DAMAGED

No

DOOR HANDLES AND/OR LATCHES INOPERABLE (HOOD, TRUNK, TAILGATE)

No

TIRES MATCH

Yes

ALL TREAD DEPTH > 4/32"

Yes

WHEEL SCUFFS, PITTING, CORROSION, OR OTHER DAMAGE

None

VEHICLE SUSPENSION

No issues

EXHAUST MODIFICATIONS

No

EMISSIONS MODIFICATIONS

No

4WD OR AWD

Yes - working

## Interior

SMART KEYS

0

## OTHER KEYS

**1**

## INTERIOR ODOR

**None**

## UPHOLSTERY OR SEATING DAMAGE

**No**

## DASHBOARD DAMAGE

**No**

## DAMAGE TO SUNROOF OR CONVERTIBLE TOP

**No**

## DAMAGE TO IN-CAR ENTERTAINMENT SYSTEM

**No**

## Mechanical

## VEHICLE STARTS

**Yes and drives**

## ACTIVE OIL OR FLUID LEAKS UNDER HOOD OR BENEATH VEHICLE

**No**

## ENGINE SLUDGE

**No**

## VEHICLE PRODUCING SMOKE

**No**

## ENGINE NOISE

**No**

## TRANSMISSION ISSUES

**No**

## OBD-II CODES/DASHBOARD LIGHTS

**No**

## SRS ISSUE

**No**

## ELECTRICAL ACCESSORY ISSUES

**No**

## VEHICLE CLIMATE CONTROL

**Working** **Contact Client Care** **866-626-4346**[Visitor Agreement](#) • [Privacy Policy](#) • [Marketplace Policy](#)