


[Return to the New InSight CR](#)

**MANHEIM ORLANDO**  
**11801 W COLONIAL DR**  
**OCOOE, FL 34761-3328**  
**(407) 656-6200**

**2018 MERCEDES-BENZ GLS GLS 450 4MATIC SUV | ALL WHEEL DRIVE | V6 CYLINDER ENGINE | A/T**

|                                    |                                |                          |
|------------------------------------|--------------------------------|--------------------------|
| Vin: 4JGDF6EE7JB138322             | Body Style: GLS 450 4MATIC SUV | Top Type: Panoramic Roof |
| Ext Color: Obsidian Black Metallic | Int Color: Black               | Odometer: 48,739 mi      |
| Work Order: 4548163                | Seller: AMERICAN BANK AUTO     | Received: 09/12/2020     |
| Inspector: Manheim Orlando         | LIQUIDATORS                    | Date:                    |
| Lane/Run: N/A                      | InService: Not Available       |                          |
|                                    | Date:                          |                          |

**VEHICLE IMAGES**

**GRADING**


- **MSRP** - \$80,180
- **Starts** - Yes
- **Drivable** - Yes

\*Process protected under U.S. Patent No. 8,230,362

**VALUE ADDED OPTIONS**

- |                        |                                  |                             |                            |
|------------------------|----------------------------------|-----------------------------|----------------------------|
| • 3rd Row Seat         | • Integrated Turn Signal Mirrors | • Power Passenger Seat      | • Smart Device Integration |
| • Back-Up Camera       | • Keyless Start                  | • Privacy Glass             | • Tire Pressure Monitor    |
| • Blind Spot Monitor   | • Multi-Zone A/C                 | • Rain Sensing Wipers       | • Woodgrain Interior Trim  |
| • Bluetooth Connection | • Navigation System              | • Running Boards/Side Steps |                            |
| • Climate Control      | • Power Driver Seat              | • Satellite Radio           |                            |
| • Heated Front Seat(s) | • Power Liftgate                 | • Seat Memory               |                            |

**VEHICLE INFORMATION**
**OPTIONS**

- |                                |                                    |                          |                                      |
|--------------------------------|------------------------------------|--------------------------|--------------------------------------|
| • A/C                          | • Child Safety Locks               | • HD Radio               | • Passenger Air Bag Sensor           |
| • Adjustable Steering Wheel    | • Cruise Control                   | • Heated Mirrors         | • Passenger Illuminated Visor Mirror |
| • AM/FM Stereo                 | • Daytime Running Lights           | • Intermittent Wipers    | • Passenger Seating 7                |
| • Auto-Dimming Rearview Mirror | • Driver Adjustable Lumbar         | • Keyless Entry          | • Power Door Locks                   |
| • Automatic Headlights         | • Driver Air Bag                   | • Knee Air Bag           |                                      |
| • Auxiliary Audio Input        | • Driver Illuminated Vanity Mirror | • Leather Steering Wheel |                                      |
| • Brake Assist                 | • Engine Immobilizer               | • Mirror Memory          |                                      |
| • Bucket Seats                 | • Floor Mats                       | • MP3 Player             |                                      |
| • Cargo Shade                  | • Front Head Air Bag               | • Pass-Through Rear Seat |                                      |
| • CD Player                    | • Front Side Air Bag               | • Passenger Air Bag      |                                      |

02 : 06 : 48

**Get Premium**

- Rear Defrost

- Rear Head Air Bag
- Remote Trunk Release
- Telematics
- Trip Computer
- Rear Side Air Bag
- Security System
- Tow Hitch
- Universal Garage Door Opener
- Rear Spoiler
- Stability Control
- Traction Control
- Variable Speed Intermittent Wipers
- Remote Engine Start
- Steering Wheel Audio Controls
- Transmission w/Dual Shift Mode

**MECHANICAL**

- 3.0L Turbocharged
- ABS Brakes
- All Wheel Drive
- Automatic Transmission
- Gasoline Fuel
- V6 Cylinder Engine

**INTERIOR**

- Interior Odor: OK
- Leather
- Odometer Operable
- Woodgrain

**TIRES AND WHEELS**

Wheels: Aluminum

| Tire        | Tread Depth | Brand     | Size      |
|-------------|-------------|-----------|-----------|
| Left Front  | 8/32"       | Pirelli   | 275/50R20 |
| Right Front | 9/32"       | Pirelli   | 275/50R20 |
| Left Rear   | 9/32"       | Pirelli   | 275/50R20 |
| Right Rear  | 9/32"       | Pirelli   | 275/50R20 |
| Spare       | N/A         | (Compact) | N/A       |

**KEYS**

- Smart - 1

**OTHER**

- Title State: Not Available
- Title Received Date: Not Available
- Org Mfg Basic Warranty: 4 Years/50,000 Miles
- \* Manheim is not responsible for voided warranties

**ADDITIONAL INFORMATION**

THIRD PARTY SELLER

**DAMAGE SUMMARY AND ADDITIONAL IMAGES**

[+ Open All Damages](#)

[- Close All Damages](#)

**— Cosmetic Conventional Paint and Body Not Required-[5 Items]**

| IMAGE | DESCRIPTION | CONDITION               | SEVERITY |
|-------|-------------|-------------------------|----------|
|       | LF Fender   | Dent/No Paint Dmg       | PDR/1    |
|       | L Qtr Panel | Mult Dents/No Paint Dmg | PDR/2    |
|       | RR Door     | Dent/No Paint Dmg       | PDR/1    |
|       | R Qtr Panel | Mult Dents/No Paint Dmg | PDR/3    |
|       | RF Door     | Dent/No Paint Dmg       | PDR/1    |

**— Paint and Body Requires Conventional Repair-[1 Items]**

| IMAGE | DESCRIPTION | CONDITION         | SEVERITY |
|-------|-------------|-------------------|----------|
|       | Lift Gate   | Dent/No Paint Dmg | 3" to 4" |

**— Miscellaneous-[2 Items]**

| IMAGE | DESCRIPTION    | CONDITION | SEVERITY             |
|-------|----------------|-----------|----------------------|
|       | Warranty Books | Missing   | Replacement Required |
|       | Owners manuals | Missing   | Replacement Required |

**— Previous Repair-[1 Items]**

| IMAGE | DESCRIPTION        | CONDITION   | SEVERITY |
|-------|--------------------|-------------|----------|
|       | Front Bumper Cover | Prev Repair | Buffable |

**IMAGE DESCRIPTION**



Misc Image



Misc Image



Misc Image



02 : 06 : 48

[Get Premium](#)



Misc Image



Misc Image



Misc Image



Misc Image



Misc Image



Misc Image



Misc Image



Misc Image

VIN: 4JGDF6EE7JB138322, Work Order: 4548163



02 : 06 : 48

Get Premium