

2016 Audi Q5 quattro 4dr 2.0T Premium Plus

WA1L2AFP6GA117534 • 97,720mi

All Wheel Drive • 2.0L 4 Cylinder Engine • Flex/Ethanol • A/T • Sun/Moonroof • Leather

Lane/Run N/A Facilitation Manheim Atlanta Seller LAKEWAY AUTO INC



Damages



No Structural Damage



No Prior Paint



Tires



AutoCheck Clean



Drivable



Starts



No Odor



Keys 1 Fobs 0



Title? (No Data)



ALL 18 EXT 6 INT 7 MISC 4 DMG 1


Announcements

- *CLEAN CARFAX/NAVIGATION

High Value Options

- Back-Up Camera
- Blind Spot Monitor
- Bluetooth Connection
- Climate Control
- Fog Lamps
- Heated Front Seat(s)
- HID headlights
- Integrated Turn Signal Mirrors
- Keyless Start
- Multi-Zone A/C
- Navigation System
- Power Driver Seat
- Power Liftgate
- Power Passenger Seat
- Premium Sound System
- Privacy Glass
- Rain Sensing Wipers
- Rear A/C
- Rear Parking Aid
- Satellite Radio
- Seat Memory
- Tire Pressure Monitor
- Woodgrain Interior Trim


Damage Overview



None ● ● ● Severe

● Structural Issue

Exterior (6)

Description	Condition Severity	Type	Image	Additional Info
● Front Bumper Cover	Bug Damage Acceptable	Miscellaneous		
● Hood	Chipped 10 or More	Paint and Body Requires Conventional Repair		
● LF Door	Dent/Paint Dmg 1/2" to 1"	Minor Damages Conventional Repairs May Be Required		
● L Qtr Panel	Mult Dents/No Paint Dmg PDR/2	Cosmetic Conventional Paint and Body Not Required		
● LR Door	Mult Dents/Paint Dmg 3	Paint and Body Requires Conventional Repair		
● Right Interior "C" Pillar Trim	Stained Permanent	Miscellaneous		

Interior (3)

Description	Condition Severity	Type	Image	Additional Info
● Owners manuals	Missing Replacement Required	Miscellaneous		
● Warranty Books	Missing Replacement Required	Miscellaneous		
● Headliner	Stained Permanent	Interior		

Structure (0)


No structural damages reported

Other (0)

No other damages reported

Tires & Wheels

Wheels Aluminum



Left Front
Yokohama
6/32"
235/55R19

Right Front
Yokohama
5/32"
235/55R19

Left Rear
Yokohama
7/32"
235/55R19

Right Rear
Yokohama
6/32"
235/55R19

Spare
(Compact)
N/A

● 6/32 +
● 5/32 to 4/32
● < 4/32
● N/A

History



No. of Historical Events	14
Last Reported Event Date	01/15/2021
Calculated Owners	3
Last Reported Mileage	97,720
Calculated Accidents	0

Title and Problem Check	✓ Vehicle checks out!
Odometer Check	✓ Vehicle checks out!
Use and Event Check	! Specific vehicle use(s) or events reported
AutoCheck Buyback Protection	✓ Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color Black	MSRP Not Available	Received Date 11/16/2020	In Service Date Not Available	Org Mfg Basic Warranty Not Available *Manheim is not responsible for voided warranties
Interior Color Black	Title State Not Available	Inspection Location Manheim Atlanta		
Top Type Sun/Moonroof	Title Received Not Available	Work Order 6095964		

Equipment

Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Automatic Headlights
- Auxiliary Audio Input
- Brake Assist
- Bucket Seats
- Cargo Shade
- CD Player
- Child Safety Locks
- Cruise Control
- Daytime Running Lights
- Driver Adjustable Lumbar
- Driver Air Bag
- Driver Illuminated Vanity Mirror
- Engine Immobilizer
- Floor Mats
- Front Head Air Bag
- Front Side Air Bag
- Headlights-Auto-Leveling
- Intermittent Wipers
- Keyless Entry
- Leather Steering Wheel
- Luggage Rack
- Mirror Memory
- MP3 Player
- Pass-Through Rear Seat
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Illuminated Visor Mirror
- Passenger Seating 5
- Power Door Locks
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Bench Seat
- Rear Defrost
- Rear Head Air Bag
- Rear Spoiler
- Remote Trunk Release
- Security System
- Stability Control
- Steering Wheel Audio Controls
- Traction Control
- Transmission w/Dual Shift Mode
- Trip Computer
- Universal Garage Door Opener
- Variable Speed Intermittent Wipers

Interior

- Leather
- Odometer Operable

Mechanical

- 2.0L Turbocharged
- 4 Cylinder Engine
- ABS Brakes
- All Wheel Drive
- Automatic Transmission
- Flex Fuel Capability

Keys

- Smart - 1

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the [Manheim Terms and Conditions](#) and the [NAAA Generic Condition Report Position Statement](#).

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

*Process protected under U.S. Patent No. 8,230,362

VIN: WA1L2AFP6GA117534,

Work Order: 6095964

© 2021 Manheim. All Rights Reserved

[Return to the classic CR](#)