

### 2016 Audi Q5 quattro 4dr 2.0T Premium Plus

WA1L2AFPOGA012794 • 93,098mi

All Wheel Drive • 2.0L 4 Cylinder Engine • Flex/Ethanol • A/T • Panoramic Roof • Leather

Lane/Run N/A Facilitation Manheim Pennsylvania Seller LANCASTER CAR COMPANY LLC



AUTOGRADE  
**3.6**  
Average

7  
Damages

No Structural Damage

No Prior Paint

9 9  
7 7  
Tires

AutoCheck  
View Report

Drivable

Starts

No Odor

Keys Fobs  
1 0

Title? (No Data)



ALL 11 EXT 2 INT 3 MISC 3 DMG 3


#### Announcements

- NAV/BANG & OLUFSEN SOUND SYS/
- title present



#### High Value Options

- Bluetooth Connection
- Climate Control
- Fog Lamps
- Heated Front Seat(s)
- HID headlights
- Integrated Turn Signal Mirrors
- Keyless Start
- Multi-Zone A/C
- Navigation System
- Power Driver Seat
- Power Liftgate
- Power Passenger Seat
- Privacy Glass
- Rain Sensing Wipers
- Rear A/C
- Satellite Radio
- Seat Memory
- Tire Pressure Monitor
- Woodgrain Interior Trim


#### Damage Overview



Exterior (6)

Description	Condition Severity	Type	Image	Additional Info
● <b>LF Door</b>	Mult Dents/Paint Dmg 10 or More	Paint and Body Requires Conventional Repair		poor pdr
● <b>LF Fender</b>	Mult Dents/No Paint Dmg 2	Minor Damages Conventional Repairs May Be Required		
● <b>LF Wheel</b>	Curb Rash 8" to 9"	Miscellaneous		
● <b>LR Wheel</b>	Curb Rash 1" to 2"	Miscellaneous		
● <b>RR Wheel</b>	Curb Rash 1" to 2"	Miscellaneous		
● <b>RF Wheel</b>	Curb Rash 1" to 2"	Miscellaneous		

Interior (1)

Description	Condition Severity	Type	Image	Additional Info
● <b>RF Seat</b>	Torn 1/8" to 1/2"	Interior		

Structure (0)


No structural damages reported

Other (0)

No other damages reported

Tires & Wheels

Wheels Aluminum



**Left Front**  
Continental  
**9/32"**  
235/60R18

**Right Front**  
Continental  
**9/32"**  
235/60R18

**Left Rear**  
Continental  
**7/32"**  
235/60R18

**Right Rear**  
Continental  
**7/32"**  
235/60R18

**Spare**  
(Compact)  
**N/A**

● 6/32 +  
● 5/32 to 4/32  
● < 4/32  
● N/A

History



No. of Historical Events	13
Last Reported Event Date	12/17/2020
Calculated Owners	1
Last Reported Mileage	93,098
Calculated Accidents	1

Title and Problem Check	✓ Vehicle checks out!
Odometer Check	✓ Vehicle checks out!
Use and Event Check	⚠ Vehicle Use or Event information available
AutoCheck Buyback Protection	✓ Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color Blue	MSRP Not Available	Received Date 11/12/2020	Work Order 6722111	Org Mfg Basic Warranty Not Available
Interior Color Gray	Title State Not Available	Inspection Location Manheim Pennsylvania	In Service Date Not Available	*Manheim is not responsible for voided warranties
Top Type Panoramic Roof	Title Received Not Available			

## Equipment

### Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Automatic Headlights
- Auxiliary Audio Input
- Brake Assist
- Bucket Seats
- Cargo Shade
- CD Player
- Child Safety Locks
- Cruise Control
- Daytime Running Lights
- Driver Adjustable Lumbar
- Driver Air Bag
- Driver Illuminated Vanity Mirror
- Driver Vanity Mirror
- Engine Immobilizer
- Floor Mats
- Front Head Air Bag
- Front Side Air Bag
- Heated Mirrors
- Intermittent Wipers
- Keyless Entry
- Leather Steering Wheel
- Luggage Rack
- Pass-Through Rear Seat
- Passenger Adjustable Lumbar
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Illuminated Visor Mirror
- Passenger Seating 5
- Passenger Vanity Mirror
- Power Door Locks
- Power Folding Mirrors
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Bench Seat
- Rear Defrost
- Rear Floor Mats
- Rear Spoiler
- Remote Trunk Release
- Security System
- Stability Control
- Steering Wheel Audio Controls
- Traction Control
- Transmission w/Dual Shift Mode
- Trip Computer
- Universal Garage Door Opener
- Variable Speed Intermittent Wipers

### Interior

- Leather
- Odometer Operable

### Mechanical

- 2.0L Turbocharged
- 4 Cylinder Engine
- ABS Brakes
- All Wheel Drive
- Automatic Transmission
- Flex Fuel Capability

### Keys

- Smart - 1

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the [Manheim Terms and Conditions](#) and the [NAAA Generic Condition Report Position Statement](#).

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

\*Process protected under U.S. Patent No. 8,230,362

VIN: WA1L2AFP0GA012794,

Work Order: 6722111

© 2021 Manheim. All Rights Reserved

[Return to the classic CR](#)