

2017 Audi Q7 3.0 TFSI Premium Plus

WA1LAAF72HD012105 • 62,386mi

All Wheel Drive • 3.0L V6 Cylinder Engine • Gas • A/T • Panoramic Roof • Leather

Lane/Run N/A Facilitation Manheim Philadelphia Seller PORSCHE AUDI WARRINGTON



Damages



No Structural Damage



No Prior Paint



Tires



View Report



Drivable



Starts



No Odor



Keys 1

Fobs 0



Title? (No Data)



ALL 18 EXT 6 INT 8 MISC 4 DMG 0




Announcements

No Announcements

High Value Options

- 3rd Row Seat
- Back-Up Camera
- Bluetooth Connection
- Climate Control
- Fog Lamps
- Heated Front Seat(s)
- Heated Steering Wheel
- HID headlights
- Integrated Turn Signal Mirrors
- Keyless Start
- Multi-Zone A/C
- Navigation System
- Power Driver Seat
- Power Liftgate
- Power Passenger Seat
- Privacy Glass
- Rain Sensing Wipers
- Rear A/C
- Rear Parking Aid
- Satellite Radio
- Seat Memory
- Smart Device Integration
- Tire Pressure Monitor
- WiFi Hotspot
- Woodgrain Interior Trim

Damage Overview



None ● ● ● Severe

● Structural Issue

Exterior (4)

Description	Condition Severity	Type	Image	Additional Info
● LR Wheel	Curb Rash 3" to 4"	Miscellaneous		
● Rear Bumper	Light Mult Scratches 10 or More	Cosmetic Conventional Paint and Body Not Required		
● Lift Gate	Heavy Mult Scratches 2	Minor Damages Conventional Repairs May Be Required		
● RR Wheel	Curb Rash 4" to 5"	Miscellaneous		

Interior (0)

No interior damages reported

Structure (0)


No structural damages reported

Other (0)

No other damages reported

Tires & Wheels

Wheels Aluminum



Left Front
Continental
6/32"
255/55R19

Right Front
Continental
5/32"
255/55R19

Left Rear
Continental
5/32"
255/55R19

Right Rear
Continental
6/32"
255/55R19

Spare
(Not Equipped)
N/A

● 6/32 +
● 5/32 to 4/32
● < 4/32
● N/A

History



No. of Historical Events	8
Last Reported Event Date	10/06/2019
Calculated Owners	2
Last Reported Mileage	7,848
Calculated Accidents	1

Title and Problem Check	✓ Vehicle checks out!
Odometer Check	✓ Vehicle checks out!
Use and Event Check	! Vehicle Use or Event information available
AutoCheck Buyback Protection	✓ Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color Black	MSRP Not Available	Received Date 02/19/2021	Work Order 8362223	Org Mfg Basic Warranty Not Available
Interior Color Black	Title State Not Available	Inspection Location Manheim Philadelphia	In Service Date Not Available	*Manheim is not responsible for voided warranties
Top Type Panoramic Roof	Title Received Not Available			

Equipment

Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Auto-Dimming Rearview Mirror
- Automatic Headlights
- Auxiliary Audio Input
- Brake Assist
- Bucket Seats
- CD Player
- Child Safety Locks
- Cruise Control
- Daytime Running Lights
- Driver Adjustable Lumbar
- Driver Air Bag
- Driver Illuminated Vanity Mirror
- Driver Vanity Mirror
- Engine Immobilizer
- Floor Mats
- Front Head Air Bag
- Front Side Air Bag
- HD Radio
- Headlights-Auto-Leveling
- Intermittent Wipers
- Keyless Entry
- Leather Steering Wheel
- Mirror Memory
- MP3 Player
- Pass-Through Rear Seat
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Illuminated Visor Mirror
- Passenger Vanity Mirror
- Power Door Locks
- Power Folding Mirrors
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Bench Seat
- Rear Defrost
- Rear Head Air Bag
- Rear Spoiler
- Remote Trunk Release
- Security System
- Stability Control
- Steering Wheel Audio Controls
- Telematics
- Traction Control
- Transmission w/Dual Shift Mode
- Trip Computer
- Universal Garage Door Opener
- Variable Speed Intermittent Wipers

Interior

- Leather
- Odometer Operable

Mechanical

- 3.0L Supercharged
- ABS Brakes
- All Wheel Drive
- Automatic Transmission
- Gasoline Fuel
- V6 Cylinder Engine

Keys

- Smart - 1

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the [Manheim Terms and Conditions](#) and the [NAAA Generic Condition Report Position Statement](#).

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

*Process protected under U.S. Patent No. 8,230,362

VIN: WA1LAAF72HD012105,

Work Order: 8362223

© 2021 Manheim. All Rights Reserved

[Return to the classic CR](#)