



Learn More

Manheim Digital Marketplace
Condition Report
Atlanta, GA 30328
(866)626-4346

VEHICLE DETAILS - 2016 MERCEDES S600 MAYBACH MAYBACH

VIN:	WDDUX7GB5GA235601	Body Style:	4DSN	Top Type:	Panoramic
Ext Color:	BLACK	Int Color:	Tan- TAN	Odometer:	40,028
Work Order:	4648750	Seller:	KELLY MOTORCARS	Received Date:	N/A
InService Date:	N/A				



GRADING



Grade 4.0 Clean

- MSRP-Not Available
- Drivable-Yes

*Process protected under U.S. Patent No. 8,230,362

VALUE ADDED OPTIONS

- Adaptive Cruise Control
- Blind Spot Monitor
- Bluetooth Connection
- CD Changer
- Cooled Front Seat(s)
- Cooled Rear Seat(s)
- Dual Zone A/C
- Entertainment System
- Hard Disk Drive Media Storage
- Heads-Up Display
- Heated Mirrors
- Heated Rear Seat(s)
- Heated Seats-Front(s)
- MP3 Compatible Stereo
- Memory Seats
- Navigation System
- Night Vision
- Premium Stereo
- Satellite Radio
- Telematics

VEHICLE INFORMATION

OPTIONS

- A/C
- ABS Brakes
- Automatic Headlights
- Back up Camera
- Brake Assist System
- Bucket Seats
- CD Player
- Child Safety Locks
- Cruise Control
- Daytime Running Lights
- Dual Air Conditioning
- Electrochromic Rearview Mirror
- Electronic Stability Control
- Engine Immobilizer
- Front Floor Mats
- Heated Steering Wheel
- Intermittent Wipers
- Keyless Entry
- Keyless Start
- Lane Departure Intervention
- Leather Steering Wheel
- Mirror Memory
- Power Folding Mirrors
- Power Mirrors
- Power Windows
- Pwr Steering
- Quad Bucket Seats
- Rain Sensing Wipers
- Rear Floor Mats
- Security System
- Steering Wheel Audio Control
- Tilt Steering
- Tire Pressure Monitor System
- Traction Control
- Trip Computer
- Turn Signal Mirrors
- Universal Garage Door Opener
- Wheel Locks
- Woodgrain Interior Package

MECHANICAL

- 12 Cylinder Gas
- Automatic
- 4X2
- 6.0 L

INTERIOR

- Odometer - 6 Digits Digital -Operable
- Int Odor: OK
- Leather - TAN

TIRES AND WHEELS

Wheels:

Tire	Tread Depth	Brand	Size
Left Front:	6/32"	Goodyear	245/40R20
Left Rear:	5/32"	Goodyear	245/40R20

KEYS

- Smart Key - 2

OTHER

- Title State:



Right Front:	6/32"	Goodyear	245/40R20
Right Rear:	8/32"	Goodyear	245/40R20
Spare:	7/32"	Other	155/80D17

■ Title Received Date: N/A

ADDITIONAL INFORMATION



DAMAGE SUMMARY AND ADDITIONAL IMAGES

Open All Damages **Close All Damages**

Cosmetic Conventional Paint and Body Not Required-[2 Items]

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Front Bumper	Prev Repair	Acceptable
	Rear Bumper	Prev Repair	Acceptable

Previous Repair-[4 Items]

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Hood	Prev Repair	SubStd Fish Eyes
	L Qtr Panel	Prev Repair	Acceptable
	LF Door	Prev Repair	Acceptable
	LF Fender	Prev Repair	Acceptable

Miscellaneous-[1 Items]











IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Rear Bumper Molding	Broken	Replacement Required

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	0000 Picture# 1	Overall Picture	
	0000 Picture# 2	Overall Picture	
	0000 Picture# 3	Overall Picture	
	0000 Picture# 4	Overall Picture	
	0000 Picture# 5	Overall Picture	
	0000 Picture# 6	Overall Picture	
	0000 Picture# 7	Overall Picture	
	0000 Picture# 8	Overall Picture	
	0000 Picture# 9	Overall Picture	
	0000 Picture# 10	Overall Picture	
	0000 Picture# 11	Overall Picture	
	0000 Picture# 12	Overall Picture	
	0000 Picture# 13	Overall Picture	
	0000 Picture# 14	Overall Picture	
	0000 Picture# 15	Overall Picture	

VIN: WDDUX7GB5GA235601, Work Order: 4648750

